

# - Firmware Changelog -



**IER-38R160005A**

**IER-38R3200005A**

## **V1.03\_180709183305 (04)**

### **New functions:**

- Auto delete per channel added
- IPV6 Address added to web menu
- DST item added in search mode menu
- Smart codec setup menu added to define ROI stream settings of network camera
- Password setting for backup of Clip viewer

### **Fixed:**

- NVR randomly reboot if VCA event mode used as alarm trigger
- If HTTPS was selected in NAT setting, camera web page was linked by HTTP mode
- If camera is deleted after several camera registration by RTSP, other cameras were influenced.
- Mobile connection was impossible when bandwidth limit is set to lower
- Dewarping mode was not available in Clipviewer

## **History**

## **V1.03\_180308144139 (03)**

### **New functions:**

- Warning message pop up when user use same IP range for WAN and POE PORT
- Display of Motion status in motion setup page
- VCA mode on/off enable in web motion setup page
- VCA object display function added to VCA setup page
- "No sub stream" warning message in, 3x3 or 4x4 layout, if IP camera set captured mode and does not support 2nd stream
- FTP (avi) file upload function added
- Camera, NVR alarm in has been seperated as NC.NO, NET(Network camera)
- Menu can be controlled by KBD-2USB (edp. 217652)
- P2P function added
- Added selection of NAT OFF, HTTP, HTTPS for every IP camera channel
- Delete button added to Notification Message menu. Allows deleting message individually.
- Rtsp port Change setup added

**Fixed:**

- Registration list show normal IP/ Zero Conf. IP are shown at the same time
- Improvement of RS485 Keyboard key input speed
- Jpeg capture image randomly missed when email notification
- If RTSP format is not correct for camera registration, NVR reboot occurred
- After Ftp upload, H.265 Data was not possible to playback
- German language was not fit into current easy installation page - GUI label width modified

**V1.03 171229123858 (02)****New functions:**

- C-protocol (H) added
- Camera Import Function added(Setup - CAMERA - Registration )
- ADUP log added
- On board Motion/ IP camera VCA were separated in EVENT- MOTION- SETUP menu
- NVR will playback 1-9min earlier from last recording time
- Settable of Max bitrate according to IP camera Max Resolution"
- P2P function added

**Fixed:**

- Email receiver setting Bug - only one account was saved
- Reboot issue when using Network Time(NTP) Sync
- Camera - Advanced Video, Stream, Video Analytics Menu combo box caused randomly save failure and system down
- Random Reboot issue When camera registration change and deletion

**V1.03 171102160709 (01)**

- In a few cases : Disconnection bug during eneo Center playback (when cursor is located to end of time line)
- Record Time is wrongly displayed in Status -> Record



### V1.03 171020003936 start version